
TRINITY UNITED METHODIST CHURCH



CORNERSTONE 2010

Building for the next century

A CAPITAL IMPROVEMENTS CAMPAIGN

- BALCONY
 Stabilize and repair the balcony structure.
- 2 WINDOWS
 Replace the windows in the educational wing.
- 3 ROOF Replace or repair church roof. Insulate attic and roof as needed.
- 4 STAINED GLASS
 Clean and repair sanctuary stained glass. Add protective covering in attic over dome. Replace missing stained glass windows.
- 5 CHIMNEY
 Point and repair masonry chimney. Replace chimney liner and water heater.
- 6 PLASTER
 Repair or replace damaged wall plaster and repaint walls.
- 7 ORGAN
 Restore the church organ and update as necessary for weekly use.
- WOODWORK
 Repair and refinish sanctuary woodwork including the floors and pews. Replace the pew cushions and restore the
 leather doors.
- SITE & FIRE
 Improve drainage around the church site
 and install retaining wall on south side.

and install retaining wall on south side. Construct fire separation wall between boiler room and adjacent rooms.

- 10 ELECTRICAL

 Update electrical including lighting, service and media.
- ELEVATOR

 Add a lift in the south entrance to provide wheelchair accessibility between the sanctuary and basement dining hall.
- 12 KITCHEN
 Remodel and update the kitchen.

Preservation consultant 515.343.6672 todd@prgia.com

NATIONAL
TRUST
FOR
HISTORIC
PRESERVATION®

This project has been funded in part by a grant from the National Trust for Historic Preservation.

Contact: Trinity United Methodist Church

515-288-4056